Approved For Release 2004/07/08 GIA-RDP81B00961R000100180067-4

OSA-4706 Copy of 4

15 October 1964

25X1 METURANDUM FOR:	
----------------------	--

SUBJECT:

Trip Report
9 October 1964 thru 13 October 1964

25X1

25X1

	Vis	ited										1964,
30.34	5 pur	cose	to a	assur	e the	ехеси	ition	lof	the			ntract
		Dis	cus	sions	ensu	ed rel	atin	je t	o th	ie	_pro	fit.
le wor	it to	great	: le	ngths	to e	xplair	i the	it t	his	was	the	lowest
profit	perc	entag	ge he	e had	ever	recei	ved	on	any	cont	ract	from
this a												

25X1

25X1 25X1

3. 13 October 1964 - Arrived at A/P facility to discuss schedule for incorporation of the new ISI instrument in the Calbun system. The question which was presented to the confidence is as follows:

That was the last date that A/P, contractor, had to receive instructions for ISI incorporation and a go-ahead by specific instrument in order to comply with present schedule. (Question essentially deals with which of the Stellar Index Camera was to be incorporated)? Further, when was he in need of the GFE Bucket to affect said integration? Either position!

His answers are as follows:

(1) Present SI configuration (ITEK) could be incorporated if instrument is received by the integration contractor (Lockheed) nine months prior to R minus 7 on each instrument.

NRO review(s) completed.

64 ILLEGIB

201

Approved For Release 2004/07/08: CIA RDP81B00961R000100180067-4

Approved For Release 2004/07/08: CIA-RDP81B00961R000100180067-4

OSA-4706

- (2) For the new ISI configuration (FCIC) A/P requires eleven months from scheduled R minus 7 on each instrument.
- (3) Properly configured Fackets are required by A/P to comply with either of the above tea months from R minus 7 date on each against This information was requested by Col. Murphy and was supplied to him on 14 October 1964.
- 4. Norther, during the course of this trip, a meeting was held with Col. Murphy for the express purpose of discussing the installation of ISI, GE Programmer and/or the reusability of recovered articles. Col. Murphy requested this meeting in order to rivise us that _____ was forwarding recommendations to Dr. _____ ian on 9 October 1964 which commendation stated the following:
- (i) The insignificant cost savings which would result from the italication of recovered herdware is not sufficient to justify the increase loss of reliability.
- (2) Concerning the ISI, the weight penelty imposed by its installation (approximately 115 lbs.) would add a severe limitation to the allowable inclination angle, specifically, it would limit the launch angle to approximately 75° and thereby provide for a marginal launch conditions.
- It was recommended by Col. Murphy that incorporation should not be considered until either more thrust was obtainable or mathods of decreasing weight throughout the balance of the system, in sufficient amount to offset the increase caused by the installation by the ISI, can be achieved.
 - 3. The incorporation of the GE Programer has also been delayed until further investigation can be conducted and assurance can be provided that no decrease in reliability would occur as a result of its incorporation.
- 4. Col. Murphy awaits instructions from Dr. McMillan ratifying the above recommendations.
- 5. Should you have any questions on the undertakings described above, please feel free to contact the undersigned.

25	X

25X1